


Figure 3A






Figure 4A




Figure 4B

marit mate Water fibritation in a

CLIENT DHCP LEASE NEGOTIATIONS

404






Figure 5A








Figure 6B





Figure 6C






Figure 7B





Figure 7C

14 / 22
INTERNAL PHONE to INTERNAL PHONE RTP FLOW






Figure 8B




Figure 8C

PHONE to MEDIA GATEWAY RTP FLOW 490B




Figure 9A




Figure 9B






Figure 9C








Figure 11